

UPDATE PRIOR SALE

UPDATE PRIOR TO SALE H446 – ELECTRIC DRIVE COOLER ISOLATION VALVE	
AFFECTED MODELS	24MY I-PACE
VOLUME AFFECTED	US 8 CAN 13
REPAIR	A concern has been identified on certain 2024 model year I-PACE vehicles where it may have been installed with an electric drive cooler isolation valve which may not operate as expected. Affected vehicles initially require a valve date code inspection. Vehicles that pass may be released for sale. Failures require the vehicle to continue to be held pending supply of replacement parts.
REPAIR TIME	Inspection: 0.3 hrs + DIDO Repair: TBA
CAMPAIGN LAUNCH	Inspection bulletin launched: August 17th, 2023 Repair bulletin is being prepared. Parts availability estimated in market by end September 2023.
Notes	Please ensure to inspect all vehicles prior to dispatch. Any failed inspection must be held and cannot be delivered until repair has been completed. In the US, there are 5 affected Waymo vehicles which have been completed. 3 remaining for retailer inspection.

UPDATE PRIOR TO SALE N819 – BATTERY HEATER COOLANT HOSE	
AFFECTED MODELS	23MY Range Rover PHEV and Range Rover Sport PHEV
VOLUME AFFECTED	US 17
REPAIR	A concern has been identified on certain vehicles where the battery heater coolant hoses may have been incorrectly installed. Affected vehicles initially require an inspection of the hose and reinstall hoses in correct position if failed. If there are damage to the coolant hoses, the vehicle will need to be held pending repair.
REPAIR TIME	0.9 -1.8 hrs + DIDO
CAMPAIGN LAUNCH	Launched on August 31st, 2023 Hose damage repair bulletin: TBA
Notes	Please use the warranty portal to identify affected vehicles and vehicles cannot be delivered until the repair has been completed.