

UPDATE PRIOR SALE N819 – BATTERY HEATER COOLANT HOSE

UPDATE PRIOR TO SALE H819 – BATTERY HEATER COOLANT HOSE	
AFFECTED MODELS	23MY Range Rover PHEV and Range Rover Sport PHEV
VOLUME AFFECTED	US 8 CAN 13
REPAIR	On certain 2023 model year Range Rover and Range Rover Sport Plug-in Hybrid Electric Vehicle (PHEV) vehicles, the battery heater coolant hoses may have been incorrectly installed. An inspection of the hose is needed, and if required the hoses will need to be reinstalled. A 2nd inspection of the coolant pipe is also required for possible pipe damage. Any vehicle with damaged pipes will need to be held pending
REPAIR TIME	Inspection: 0.9 hrs + DIDO Repair: 1.8 hrs + DIDO
CAMPAIGN LAUNCH	Inspection bulletin launched: August 31st, 2023 Repair bulletin to be released pending parts receipt
Notes	Please ensure to inspect all vehicles prior to dispatch. Any failed inspection must be held and cannot be delivered until repair has been completed.