HEADLAMP WASHER JETS LEAKING

Customer Voice:

• The headlamp washer jet nozzles are leaking fluid when not operating the washers.

Technical Description:

• The check valve in the headlamp washer jet hose assembly may not be sealing properly, allowing washer fluid to siphon out of the wiper jet nozzles.

Status:

- SSM 76076 has been published to address this concern.
- Revised washer one-way check valves are being introduced in production.
- The check valves are only serviced as a headlamp washer hose assembly.

Defender

• 20-23MY Defender

