

WIND/TAPPING NOISE FROM EXTERIOR A-PILLAR/WINDSHIELD AREA AT MOTORWAY SPEEDS

Customer Voice:

- There is a wind or tapping type noise from the windshield area while driving.

Technical Description:

- There may be a noise concern where the exterior windshield trim contacts the windshield.

Status:

- Engineering is currently investigating reports of a wind or tapping type noise in the exterior A-pillar area.
- To support this investigation, **SSM 76042** has been published requesting an EPQR be submitted with details of the concern.

Defender

- 22–23MY Defender

