

2023 Ontour

REPAIR 1: Awning is not level. When awning is extended awning is leaning to the left. left side awning arm needs to be set lower by lifting arm and fastening the front bolt in awning arm base and fastening the hex screw. REQUESTING: .5 HRS **0.50 approved.**