

2022 Ascent

JF 9.18.23 Greg called,

he said they were travelling on an interstate at 75 mph when the awning deployed about 18 inch of awning was out.

This is a failed winch on the awning.

I spoke with my tech and he suggested new fabric and a replacement winch assembly. He suggested that the repair location checks the lead bar alignment when they install the fabric, to make sure that it is aligned properly with the limit switch to cut power to the motor when the awning is closed.