GPOP - Issue Review System

Part Number: 68565498A\$, 68565499A\$, 68616096A\$, 68616097A\$

Part Description: Motor, Power Running Board

Issue For issues with a stuck or binding power side step, DO NOT replace the motor or hinge(s).

Description: The hinges must be cleaned and lubricated at regular intervals. See latest version of Star Online #S2223000044, the vehicle owner's manual, or published service information in

Service Library.

Replacements of the motor and hinge assembly due to lack of maintenance could be

subject to chargeback.