



STAR ONLINE PUBLICATION



Case Number: S2323000076

Release Date: September 2023

Symptom/Vehicle Issue: Cargo tie down not sitting flush to rear interior quarter trim panel.

Diagnosis:



This document does not authorize warranty repairs. This communication documents a record of past experiences. STAR Online does not provide any conclusions about what is wrong with the vehicle. Rather, it captures all previous cases known that appear to be similar or related to the vehicle symptom / condition. You are the expert, and you are responsible for deciding on the appropriate course of action.

Contact STAR Center, or your Technical Assistance Center Via TechConnect, eCONTACT or Service Library entry if no solution is found.



STAR ONLINE PUBLICATION



Repair Procedure:

Remove the quarter trim panel per service library 23 - Body / Interior / PANEL, Quarter Trim / Removal and Installation.

Apply foam tape to the backside of the trim panel around the tie down hole, to reduce the gap when reinstalled.

Verification:

Verify the gap is acceptable.

This document does not authorize warranty repairs. This communication documents a record of past experiences. STAR Online does not provide any conclusions about what is wrong with the vehicle. Rather, it captures all previous cases known that appear to be similar or related to the vehicle symptom / condition. You are the expert, and you are responsible for deciding on the appropriate course of action.

Contact STAR Center, or your Technical Assistance Center Via TechConnect, eCONTACT or Service Library entry if no solution is found.