

Technical Service Bulletin

01 PSS MIL on DTC P240700 Evap leak detection pump circuit

01 23 82 2066675/5 October 16, 2023. Supersedes Technical Service Bulletin Group 01 number 23-55 dated April 10, 2023, for reasons listed below.

| Model(s) | Year | VIN Range | Vehicle-Specific Equipment |
|--|-------------|-----------|----------------------------|
| A3, S3, RS 3, A6, A6 allroad, S6, RS 6 Avant, A7, S7, RS 7, A8, S8, Q3, Q5, Q5 Sportback, Q7, SQ7, Q8, SQ8, RS Q8, R8, R8 Spyder, TT, TTS, and TT Roadster | 2022 – 2023 | All | Gasoline Engine |
| Q5 e quattro, SQ5, SQ5 Sportback, and TT RS | | | |

Condition

| REVISION HISTORY | | | |
|------------------|------------|---|--|
| Revision | Date | ate Purpose | |
| 5 | - | Revised Service (updated expected release date) and header (updated models) | |
| 4 | 04/11/2023 | Revised Warranty (updated statement) | |
| 3 | 04/07/2023 | Revised header (updated models) | |

This bulletin only applies to Model Year 2022 and 2023 Gasoline Engines.

Customer states:

• MIL Light On.

Workshop findings:

The following DTC may be stored Passive/Static in the Engine control module, J623 (address word 001):

• DTC P240700 Evap emission control system leakage diagnosis pump current fluctuating

The event memory must not contain further relevant entries.

Technical Background



Technical Service Bulletin

Not applicable.

Production Solution

This bulletin will be updated when more information is available. A solution is currently under development.

Service

- 1. Delete **DTC P240700** and release the vehicle to the customer.
- 2. Explain to the customer that a solution is expected to be available by the end of the 2nd quarter of 2024 (subject to change) and no repairs are necessary at this point. Do not replace any components for this condition since it will not resolve the customer's concern.
- 3. Create a PSS record in the PSS application through the Pending Service Solutions (PSS) link in Access Audi (under *Related Links* >> *Service*), or through the Technical Assistance page in Elsa.

For 2023 Q5 vehicles, please refer to TSB 2071770: 01 MIL on, DTC P240700 Leak Detection Pump Current Fluctuating.

Warranty

This TSB is informational only and not applicable to any Audi Warranty.

Additional Information

All parts and service references provided in this TSB (2066675) are subject to change and/or removal.

©2023 Audi of America, Inc. All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies, and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites without the prior expressed written permission of the publisher.