



Subject: SPECIAL SERVICE PROGRAM - SSPD3 - 2024 CX-90 (PHEV) - OBD II AC REFRIGERANT PRESSURE DETECTION CONCERN	Campaign No.: SSPD3
	Last Issued : 10/26/2023

DESCRIPTION

Attention All Mazda Dealers. Please read the Dealer Email Announcement below before performing repairs. The repair procedure is available and repairs can begin immediately on all vehicles at your dealer or arriving through the service drive.

SSPD3- 2024 CX-90 (PHEV) - OBD II AC Refrigerant Pressure Detection Concern: On certain CX-90 vehicles, air conditioner refrigerant pressure malfunction may not be judged correctly due to inappropriate failure judgement program of PCM. The repair will be reprogramming the PCM and ECU with the modified software with MMDS, using MDARS. There are 6,089 vehicles in the campaign.

CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "do-it-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.