

Subject: DOOR GARNISH GAP	Service Alert No.: SA-064/23
	Last Issued : 10/17/2023

BULLETIN NOTES

APPLICABLE MODEL(S)/VINS

2024 CX-90

DESCRIPTION

Some customers or dealerships will report a gap at the door garnish (trim).



Customers having this concern should have their vehicle repaired using the following repair procedure.

REPAIR PROCEDURE

1. Verify the customer concern,
2. Replace the rear glass run channel on the affected door(s) using the LEFT FRONT DOOR GLASS RUN-CHANNEL REMOVAL/INSTALLATION, RIGHT FRONT DOOR GLASS RUN-CHANNEL REMOVAL/INSTALLATION, or REAR DOOR GLASS RUN-CHANNEL REMOVAL/INSTALLATION procedure.
3. Verify the repair.

PARTS INFORMATION

CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "do-it-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.

Parts Number	Description	Qty.	Notes
KMV65960XB	GLASS CHANNEL (L)	1	Left Front Door
KMV65860XB	GLASS CHANNEL (R)	1	Right Front Door
KMV67360XA	GLASS RUN CHANNEL (L)	1	Left Rear Door
KMV67260XA	GLASS RUN CHANNEL (R)	1	Right Rear Door

CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "do-it-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.