# Technical Service Bulletin

Mazda North American Operations Irvine, CA 92618-2922



## Subject:

NOISE COMPLAINTS FROM FRONT COMBINATION LIGHT

Bulletin No.: 09-015/23

Last Issued : 10/06/2023

### **BULLETIN NOTES**

This bulletin supersedes the previously issued bulletin(s) listed below. The changes are noted in Red text.

Previous TSBs:	Date(s) Issued:
SA-013/23	03/07/23
09-015/23	02/24/23, 07/26/23 and <mark>08/29/23</mark>

# APPLICABLE MODEL(S)/VINS

2020-2022 CX-30 (Mexico built) vehicles produced before Mar. 3, 2022 2022 MX-30 vehicles with VINs lower than JM1 DR\*\*\*\* \*\* 100445 (Produced before Sept. 24, 2021) 2022 CX-5 vehicles with VINs lower than JM3 KF\*\*\*\* \*\* 649504 (Produced before Aug. 2022) 2023 CX-5 vehicles with VINs lower than JM3 KF\*\*\*\* \*\* 237775 (Produced before Mar. 2023)

# DESCRIPTION

Some customers may notice an abnormal noise (i.e. whine, groan, rattle or squeak) coming from the front combination lights when turning them on, or a few minutes after turning them off.

The noise may be due to contamination by foreign matter during the manufacturing process. The fan motor bearing may become worn out during use. To eliminate the noise, the production process at the supplier and the material has been modified.

**NOTE:** It is normal for some noise to occur within the first few seconds after starting the engine, when the front combination lights perform a self check (sweep).

# **REPAIR PROCEDURE**

1. Verify the customer complaint.

2. Replace the front combination light(s) with modified parts according to the instructions on MGSS online:

- CX-30: (FRONT COMBINATION LIGHT REMOVAL/INSTALLATION)
- MX-30: (FRONT COMBINATION LIGHT REMOVAL/INSTALLATION)
- CX-5: (FRONT COMBINATION LIGHT REMOVAL/INSTALLATION)

Page 1 of 7

**CONSUMER NOTICE:** The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "doit-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.

3. Verify the repair.

Page 2 of 7

**CONSUMER NOTICE:** The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "doit-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.

Bulletin No.: 09-015/23	Last Issued : 10/06/2023
-------------------------	--------------------------

# PARTS INFORMATION

CX-30:

Parts Number	Description	Qty.	Notes
DLLM-51-040	LAMP-HEAD.LH	1	
DLLM-51-030	LAMP-HEAD.RH	1	
DGJ1-51-040B	LAMP-HEAD.LH	1	North America, Mexico built
DGJ1-51-030B	LAMP-HEAD.RH	1	North America, Mexico built
DGH9-51-040A	LAMP-HEAD.LH	1	
DGH9-51-030A	LAMP-HEAD.RH	1	

#### MX-30:

Parts Number	Parts Number Description		Notes	
DN4G-51-040A	LAMP-HEAD.LH	1		
DN4G-51-030A	LAMP-HEAD.RH	1	North Amorica, Mavias built	
DN4E-51-040	LAMP-HEAD.LH	1	North America, Mexico built	
DN4E-51-030	LAMP-HEAD.RH	1		

#### CX-5:

Parts Number	Description	Qty.	Notes	
KPF1-51-041A	LAMP-HEAD.LH	1		
KPF1-51-031A	LAMP-HEAD.RH	1	North America	
KPF3-51-041A	LAMP-HEAD.LH	1	North America	
KPF3-51-031A	LAMP-HEAD.RH	1		

## NOTE:

- Refer to the GEPC to select the applicable part number.
- The part numbers have not been changed.
- All units in stock are modified parts.

Page 3 of 7

**CONSUMER NOTICE:** The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "doit-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.

Bulletin No.: 09-015/23	Last Issued : 10/06/2023
-------------------------	--------------------------

#### WARRANTY INFORMATION

NOTE:

- This warranty information applies only to verified customer complaints on vehicles eligible for warranty repair.
- This repair will be covered under Mazda's New Vehicle Limited Warranty term.
- Additional diagnostic time cannot be claimed for this repair.

Warranty Type	A
Symptom Code	82
Damage Code	9G
Part Number Main Cause	****-51-030* or ****-51-040* (CX-30 / MX-30) ****-51-031* or ****-51-041* (CX-5)
Quantity	1
Operation Number / Labor Hours:	Refer to the tables below

NOTE: If necessary, claim opposite side head lamp as a related part.

# CX-30:

VARIATION 1	VARIATION 2	VARIATION 3	VARIATION 4	VARIATION 5	LABOR OPERATION NUMBER	LABOR TIME
360°view monitor With 360° view monitor verification and		With front cross traffic alert (FCTA) system		XXW9HBRX	1.2	
	Both sides	Without front cross traffic alert (FCTA) system	With mazda radar cruise control (MRCC) system	XXW9HBRX	1.2	
		Without front cross traffic alert (FCTA) system	Without mazda radar cruise control (MRCC) system	XXW9HDRX	1.0	
System	system 360°view monitor system aiming		With front cross traffic alert (FCTA) system		XXW9HHRX	1.0
	One side	Without front cross traffic alert (FCTA) system	With mazda radar cruise control (MRCC) system	XXW9HHRX	1.0	
			Without front cross traffic alert	Without mazda radar cruise	XXW9HJRX	0.9

#### Page 4 of 7

**CONSUMER NOTICE:** The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "doit-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.

Bulletin No.: 09-015/23

			(FCTA) system	control (MRCC) system		
	360°view monitor system screen display verification only	Both sides	With front cross traffic alert (FCTA) system		XXW9HCRX	1.1
			Without front cross traffic alert (FCTA) system	With mazda radar cruise control (MRCC) system	XXW9HCRX	1.1
		Both sides	Without front cross traffic alert (FCTA) system	Without mazda radar cruise control (MRCC) system	XXW9HERX	0.9
With 360° view monitor system	360°view monitor system screen display verification only		With front cross traffic alert (FCTA) system		XXW9HHRX	1.0
		One side	Without front cross traffic alert (FCTA) system	With mazda radar cruise control (MRCC) system	XXW9HJRX	0.9
			Without front cross traffic alert (FCTA) system	Without mazda radar cruise control (MRCC) system	XXW9HKRX	0.8
			With front cross traffic alert (FCTA) system		XXW9HCRX	1.1
			Without front cross traffic alert (FCTA) system	With mazda radar cruise control (MRCC) system	XXW9HCRX	1.1
Without 360°view monitor system			Without front cross traffic alert (FCTA) system	Without mazda radar cruise control (MRCC) system	XXW9HFRX	0.8
		One side	With front cross traffic alert (FCTA) system		XXW9HJRX	0.9
			Without front cross traffic alert (FCTA) system	With mazda radar cruise control (MRCC) system	XXW9HJRX	0.9
			Without front cross traffic alert (FCTA) system	Without mazda radar cruise control (MRCC) system	XXW9HLRX	0.7

#### Page 5 of 7

**CONSUMER NOTICE:** The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "doit-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.

MX-30:

VARIATION 1	VARIATION 2	VARIATION 3	VARIATION 4	LABOR OPERATION NUMBER	LABOR HOURS
		360°view monitor system screen display verification and 360°view monitor system aiming		XXW9HBRX	1.2
Both sides	With 360°view monitor system	360°view monitor system screen display verification only	With front cross traffic alert (FCTA) system	XXW9HBRX	1.2
Without 360°view mon system		360°view monitor system screen display verification only	Without front cross traffic alert (FCTA) system	XXW9HCRX	1.1
	360°view monitor			XXW9HCRX	1.1
One side		360°view monitor system screen display verification and 360°view monitor system aiming		XXW9HHRX	1.0
	With 360°view monitor system	360°view monitor system screen display verification only	With front cross traffic alert (FCTA) system	XXW9HHRX	1.0
		360°view monitor system screen display verification only	Without front cross traffic alert (FCTA) system	XXW9HJRX	0.9
	Without 360°view monitor system			XXW9HJRX	0.9

Page 6 of 7

**CONSUMER NOTICE:** The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "doit-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.

Bulletin No.: 09-015/23	
-------------------------	--

CX-5:

VARIATION 1	VARIATION 2	VARIATION 3	VARIATION 4	LABOR OPERATION NUMBER	LABOR HOURS
Both sides	With 360°view monitor system	With 360° view monitor system screen display verification	With 360° view monitor system aiming	XXW9HCRX	1.0
		With 360° view monitor system screen display verification	Without 360° view monitor system aiming	XXW9HDRX	0.9
	Without 360°view monitor system	Without 360° view monitor system screen display verification	Without 360° view monitor system aiming	XXW9HFRX	0.7
One side	With 360°view monitor system	With 360° view monitor system screen display verification	With 360° view monitor system aiming	XXW9HPRX	0.8
		With 360° view monitor system screen display verification	Without 360° view monitor system aiming	XXW9HNRX	0.7
	Without 360°view monitor system	Without 360° view monitor system screen display verification	Without 360° view monitor system aiming	XXW9HMRX	0.6

Page 7 of 7

**CONSUMER NOTICE:** The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "doit-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.