

Service Bulletin

INFORMATION

Subject:	Visible Cracks in Shock Tower Near Strut Top Mount
----------	--

Brand:	Model:	Model Year:		VIN:		Engine	Transmission:
		from	to	from	to	Engine:	Transmission.
Chevrolet	Camaro	2016	2024	—	—	All	All

Involved Region or Country Europ	n America, Argentina, Brazil, Chile, Colombia, Ecuador, Paraguay, Peru, Uruguay, pe, Russia, Middle East, Israel, Palestine, Japan, GM Korea Company, China, an, Thailand, Singapore, Philippines, Africa
----------------------------------	---



Important: Service agents must comply with all International, Federal, State, Provincial, and/or Local laws applicable to the activities it performs under this bulletin, including but not limited to handling, deploying, preparing, classifying, packaging, marking, labeling, and shipping dangerous goods. In the event of a conflict between the procedures set forth in this bulletin and the laws that apply to your dealership, you must follow those applicable laws.

Version	3
Modified	Released May 14, 2019 Revised October 02, 2020 – Added the 2020 and 2021 Model Years and updated the Involved Region or Country section. Revised October 12, 2023 – Added the 2022-2024 Model Years and the Important statement.

GM bulletins are intended for use by professional technicians, NOT a "<u>do-it-yourselfer</u>". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, <u>DO NOT</u> assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION