



TECHNICAL SERVICE BULLETIN

2.3L EcoBoost - Illuminated Malfunction Indicator Lamp (MIL) With DTCs P0300 And/Or P0316 Stored In The PCM

23-2314

03 October
2023

Model:

Ford 2024 Mustang	Engine: 2.3L EcoBoost
----------------------	-----------------------

Issue: Some 2024 Mustang vehicles equipped with a 2.3L EcoBoost engine may exhibit an illuminated MIL with diagnostic trouble codes (DTC) P0300 and/or P0316 stored in the powertrain control module (PCM). The vehicle may also run rough during a cold start. This may be due to the software in the PCM. To correct this condition, perform the Service Procedure below to reprogram the PCM using the latest software level of the Ford Diagnosis and Repair System (FDRS) diagnostic scan tool.

Action: Follow the Service Procedure to correct the condition on vehicles that meet all of the following criteria:

- 2024 Mustang
- 2.3L EcoBoost engine
- Illuminated MIL with DTCs P0300 and/or P0316 stored in the PCM

Warranty Status: Eligible under provisions of New Vehicle Limited Warranty (NVLW)/Emissions Warranty/Service Part Warranty (SPW)/Special Service Part (SSP)/Extended Service Plan (ESP) coverage. Limits/policies/prior approvals are not altered by a TSB. NVLW/Emissions Warranty/SPW/SSP/ESP coverage limits are determined by the identified causal part and verified using the OASIS part coverage tool.

Labor Times

Description	Operation No.	Time
2024 Mustang 2.3L: Retrieve DTCs And Reprogram The PCM (Do Not Use With Any Other Labor Operations)	232314A	0.4 Hrs.

Repair/Claim Coding

Causal Part:	RECALEM
Condition Code:	04

Service Procedure

1. Reprogram the PCM using the latest software level of the FDRS diagnostic scan tool.

NOTE: Advise the customer this vehicle is equipped with an adaptive transmission shift strategy which allows the vehicle's computer to learn the transmission's unique parameters and improve shift quality. When the adaptive strategy is reset, the computer will begin a relearning process. This relearning process may result in firmer than normal upshifts and downshifts for several days.

© 2023 Ford Motor Company
All rights reserved.

NOTE: The information in Technical Service Bulletins is intended for use by trained, professional technicians with the knowledge, tools, and equipment to do the job properly and safely. It informs these technicians of conditions that may occur on some vehicles, or provides information that could assist in proper vehicle service. The procedures should not be performed by "do-it-yourselfers". Do not assume that a condition described affects your car or truck. Contact a Ford or Lincoln dealership to determine whether the Bulletin applies to your vehicle. Warranty Policy and Extended Service Plan documentation determine Warranty and/or Extended Service Plan coverage unless stated otherwise in the TSB article. The information in this Technical Service Bulletin (TSB) was current at the time of printing. Ford Motor Company reserves the right to supersede this information with updates. The most recent information is available through Ford Motor Company's on-line technical resources.