



WARRANTY ENHANCEMENT PROGRAM (WEP)

USE ONLY IF FAILURE IS PRESENT

**COE TURBOCHARGER – AAWE0
SUPERSEDES WEP AAGM0**

**BULLETIN NO: WP-23-005
DATE: 10-31-2023
REF: QA-231025-N1**

SUBJECT VEHICLES: Certain 13MY-20MY Cab-Over Engine (COE) Trucks equipped with a J05 engine.

OVERVIEW:

May exhibit an internal oil leak that could negatively impact operation of the Variable Nozzle and cause the MIL (malfunction Indicator Light) to illuminate.

If this condition is found, refer to the appropriate Vehicle Identification Number in the warranty system to determine vehicle eligibility.

Warranty Terms

Perform this repair ONLY if failure condition is present.

-Warranty enhancement program: 10 years with no mileage limitation from the delivery date to the initial end purchaser, or five (5) years from the date of the customer notification letter, whichever is longer, will be covered by this program.

For any other failure modes, standard warranty conditions will be applied.



PARTS:

Part Number	Part Description	Quantity	
17201E0A85	Turbocharger Sub-Assy	1	
Gasket Kit Part Number – HN001234300	S241091860	Gasket - Turbo To Exh Manifold	1
	SZ17810007	Nut	7
	SZ12610015	Bolt Stud -Manifld To Exh Pipe	4
	S241791430	Gasket - Compressor Outlet	1
	SL72201210	Gasket - Turbo Oil Inlet Pipe	8
	SL72201415	Gasket - Turbo Oil Inlet Pipe	2
	S241351161	Gasket - Oil Outlet	1
	SZ43014003	Gasket - Turbo Water & Fuel	6
	15472E0050	Gasket - Oil Outlet	1
	SZ91016223	Spacer	7
	17451E0110	Gasket - Exhaust Pipe	1
	SZ11610171	Stud	3
	1745178061	Gasket - Exhaust Pipe	1
	17451E0121	Gasket - Exhaust Pipe	1
	S171041580	Gasket Sub Assy Exh Mfld	1
	25634E0010	Gasket Sub Assy Exh Mfld	2



BEFORE YOU BEGIN:

- Read and understand all instructions and procedures before you begin the work.
- Read and follow all **WARNINGS** and **NOTICES** set forth in this publication. These alerts help to avoid damage to components, serious personal injury, or both.
- Park the vehicle on a flat, level and solid surface.
- Place the gear shift lever in "Neutral" or "Park".
- Apply the parking brake firmly and confirm parking brake activation.
- Turn off the engine and remove the key from the ignition switch.
- Always wear safety glasses or goggles to protect your eyes.
- Place wheel chocks in front of and behind all the wheels to prevent the vehicle from moving.

REPAIR PROCEDURE:

Please refer to the Hino Service Manual for replacement instruction.
(Turbocharger J05E)

CLAIM APPLICATION

Reimbursable in accordance within the terms and policies of the Hino limited warranties.

Turbocharger Replacement:

- a) Campaign No: AAWE0
- b) Labor charge: 3.5 hours (Includes 0.5 hr. diagnostic time)
- c) Warranty code: 86130
- d) Trouble code: 98
- e) Operation code: 08101ARE
- f) Original failed part: 9999999999

