

CRITICAL CONCERNS & FIELD SERVICE ACTIONS

UPDATE PRIOR SALE H446 – I-PACE ELECTRIC DRIVE COOLER ISOLATION VALVE

UPDATE PRIOR TO SALE H446 – ELECTRIC DRIVE COOLER ISOLATION VALVE	
AFFECTED MODELS	24MY I-PACE
VOLUME AFFECTED	US 8 CAN 13
REPAIR	A concern has been identified on certain 2024 model year I-PACE vehicles where it may have been installed with an electric drive cooler isolation valve which may not operate as expected. Affected vehicles initially require a valve date code inspection. Vehicles that pass may be released for sale. Failures require the vehicle to continue to be held pending supply of replacement parts.
REPAIR TIME	Inspection: 0.3 hrs + DIDO Repair: 2.50 hrs + DIDO
CAMPAIGN LAUNCH	Inspection bulletin launched: August 17th, 2023 Repair bulletin launched Sept 11 th , 2023
Notes	Please ensure to inspect all vehicles prior to dispatch. Any failed inspection must be held and cannot be delivered until repair has been completed 6 open VIN remain.