

SV Signature Suite – 2nd Row Deployable Table Not Stowing

Customer Voice:

- The 2nd row deployable table is not stowing and stays deployed.

Technical Description:

- The deployable table for the 2nd row seats may not stow once deployed due to a fault with a microswitch in the table assembly.

Status:

- The microswitch has now been made serviceable less the complete table assembly.
- **SSM 76094** has been published to address this concern, providing repair guidance.

Range Rover

- 23MY Range Rover (SV model variants Only)

