

Replacement Module Programming Routine

Customer Voice:

- The headlamps not fully functioning properly after module replacement.

Technical Description:

- Engineering investigations of concerns have found that in some instances, new replacement headlamp and power steering modules were not properly programmed when replaced.
- When replacing headlamp or power steering modules, the new module MUST be programmed as a new module when installed, as per the Workshop Manual procedures.

Status:

- SSM 76100 & SSM 76101 have been published to remind servicing technicians of this requirement that is within the workshop procedures.

Range Rover

- 21-24MY Range Rover
- 21 – 24MY Sport
- 21 – 24MY Evoque
- 21-24MY Velar

Defender

- 20–24MY Defender

Discovery

- 21 -24MY Discovery
- 21-24MY Discovery Sport

Jaguar

- 21-24MY E-PACE
- 21-24MY F-PACE
- 21-24MY I-PACE
- 21-24MY XF

