

ROOF OPENING PANEL STICKING IN TILT OPERATION

Customer Voice:

- The roof opening panel sticks in the tilt position during high ambient temperatures.

Technical Description:

- This may be caused by the lubricating grease for the tilt arm assemblies failing during high temperatures, causing the tilt mechanical lever to stick.

Status:

- SSM 76029 has been published to provide repair guidance.

Defender

- 23MY Defender

