

# McLaren Artura - Flywheel Ring Gear Retention Enhancement

SENSITIVITY: Restricted


<b>Bulletin type:</b>	Service Campaign
<b>Reference number:</b>	N/A
<b>Campaign reference:</b>	SCB 16 F 001
<b>Attention:</b>	Retailer Aftersales Managers, Retailer Service Managers, Retailer Service Advisors, Retailer Technicians, Retailer Parts Managers
<b>Affected vehicles:</b>	McLaren Artura
<b>Situation:</b>	Addition of Loctite 262 to the flywheel ring gear fixing bolts
<b>Procedure:</b>	Action affected vehicles during next annual service visit. Please refer to the information outlined in this document to complete the required work
<b>Date:</b>	10 October 2023

This bulletin will cover:

- 
1. Overview
  2. Parts information
  3. Procedure
  4. Warranty Information
  5. Affected Vehicles
- 

## 1. Overview

Through continuous product quality monitoring, McLaren Automotive has released an improved fixing procedure for the flywheel ring gear bolts which now includes the addition of Loctite. A rework procedure is outlined in this document. McLaren Automotive requests Retailers to carry out this rework during the next annual service visit of the vehicles affected by this campaign.



**Image 1** Location of flywheel ring gear bolts (1)

## 2. Parts information

To complete this rework, Loctite 262 which can be sourced locally, is required.

The flywheel ring gear bolts should be reused.

No other parts are required during this rework.

## 3. Procedure

To perform the required work, follow instruction 'SCB 16 F 001 - Flywheel Ring Gear Rework Work Instructions' which has been attached with this document. This contains the relevant work instructions and care points to ensure the required work is carried out to bring the vehicle up to current manufacturing standard.

**Care Point:** This rework is to be carried out during the vehicles next annual service

## 4. Warranty Information

Submit a claim to the McLaren Warranty department following completion of the work, using the following details.

Description	Repair Time
McLaren Artura – Flywheel ring gear – next annual service	0.80 hrs

## 5. Affected Vehicles

Affected vehicles will be flagged in the Retailer Portal when next opening a Workshop Visit related to the vehicle. Your Regional Aftersales Manager will also contact you with a VIN list of affected vehicles.

If you have any questions, please speak to your Regional Aftersales Manager.

The information contained in McLaren bulletins is for internal use only by McLaren Authorised Retailers and must not be published on external websites or social media forums etc.

The McLaren data classification policy applies to all full time, part-time and fixed term employees of McLaren and all workers including, contractors, consultants, suppliers, and third parties who have access to McLaren data and/or systems. This policy includes all information held by, or on behalf of, McLaren in any form and all information systems/services used by, or used to store data belonging to, McLaren.

Part numbers listed in McLaren bulletins are for reference only. Always check with the parts department to verify the latest part numbers.

All bulletins (Information/Campaign/Recall) issued by McLaren Automotive Limited ("McLaren") are intended only for use by technicians who have attended McLaren technical training courses. McLaren trained technicians have the equipment, tools, safety instructions and the know how to perform the job properly and safely. McLaren bulletins are written to inform McLaren technicians of conditions that may occur on some McLaren vehicles, or to provide information that could assist diagnosing a McLaren vehicle. Part numbers listed in McLaren bulletins are for reference only. Always check with the parts department to verify the latest part numbers.