

WPK3 Workshop campaign - Checking wire harness for rear cover and reworking if necessary

WPK3 Workshop campaign - Checking wire harness for rear cover and reworking if necessary

ID Number	WPK3
Models	Panamera (971)
Model Years	2023
VIN List	Attached
Number of Affected VINs	44
Issue Description	<p>Potentially faulty wiring harnesses were installed in the rear cover.</p> <p>If this is the case, the heated rear window may malfunction, and result in interference to radio reception.</p> <p>For this reason, the wiring harness for the rear cover of the affected vehicles must be tested and reworked if necessary.</p>
What should Porsche Centers do?	<p>Please arrange for this measure to be carried out as soon as possible on affected vehicles.</p> <p>As of the time of this posting (10/19/23) the remedy is now available.</p> <p>1 repair kit (PNAWPK30001) has been allocated to each of the 36 Porsche Centers with an affected vehicle UIO. Additional kits can be ordered via PPL Order with PRMS Parts Support ticket for release. The PRMS Ticket must contain the PPL Order # in the ticket.</p>
TI Number	No. 122-23

Warranty processing

WPK3 Workshop campaign - Checking wire harness for rear cover and reworking if necessary

Validity:

This workshop campaign will be carried out up to September 4th, 2028 and will be closed on that date.
Please note that warranty claims can only be processed up to this date.

Scope 1: Checking wire harness for rear lid

Damage Number	WPK3 66 000
Repair Code	1
Labor time	65 TU

Scope 2: Reworking wire harness for rear lid

Damage Number	WPK3 66 000
Repair Code	2
Labor time	109 TU

Please enter the campaign carried out in the Warranty and Maintenance Logbook for the vehicle.

Customer mobility

If requested, mobility for the affected customer can be ensured by offering a suitable replacement vehicle.
Please invoice this additional service via WWS with the campaign scope.

Attachments

1. [VIN_List_Report_WPK3_2023-10-19_V2.xlsx](#)