Subject: Engineering Information - (El Lite) - (Pictures Only) Engine Coolant Leak Due to Improperly Seated Hoses and/or Loose Clamps

This PI has been revised to end the need for gathering information from the field. Please discard PIE0757.

Brand:	Model:	Model Year:		VIN Breakpoint:		Engine:	Transmission:
		from	to	from	to		
Buick	Enclave	2023	2023	_	_	_	_
Chevrolet	Traverse						

If you encounter a vehicle with the above condition, refer to SI for further diagnosis.

Version	2
Modified	Released August 01, 2023 November 08, 2023 - Ended the need for gathering further information from the field.