

		Tesla, Inc. Service Bulletin		<i>Replace Passenger Side Wiper Arm Assembly</i>	
SB-23-17-009 October 13, 2023					
Classification		Section/Group		Mobile Service	Configuration
Repair Bulletin		17 - Electrical		Can Perform (where permitted)	LHD
Model Year	Model	Country/Region		Build Location	
2023	Model Y	North America		Fremont	
The model(s) and model year(s) listed are a general approximation of the affected VIN list. Refer to the VIN/Bulletin Tracker or Customer/Vehicle profile to determine applicability of this bulletin for a particular vehicle.					

This repair bulletin provides instructions on addressing a possible customer concern regarding the operation of Tesla vehicles. These instructions should only be performed by trained professionals.

Condition

On some Model Y vehicles built at Fremont, the passenger side windshield wiper arm may make a ticking noise when the wiper is in operation.

 **NOTE:** The ticking noise does not affect the passenger side windshield wiper performance.

Correction

Upon complaint, inspect the vehicle for the condition. If the condition is present, replace the passenger side wiper arm assembly.

Correction Description	Correction	Time
SB-23-17-009 Not Applicable	S012317009	0.00
Replace Passenger Side Wiper Arm Assembly	S022317009	0.12

	Part Number	Description	Quantity
Parts Required	1658938-00-A	ARM AND BLADE ASSEMBLY PASSENGER LEFT HAND DRIVE	1

This part number was current at the time of publication. Use the revision listed or later, unless otherwise specified in the [Parts Catalog](#).

Special Tools 1058696-00-A Wiper Arm Removal Tool

Procedure

Replace the passenger side wiper arm assembly (refer to Service Manual procedure [17500352](#)).