

Technical Service Bulletin

91 Remote park assist plus not working - myAudi app message "Connection to vehicle required" 91 23 44 2071986/1 November 6, 2023.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment	
e-tron GT, and RS e-tron GT	2022 – 2024			
e-tron quattro, e- tron Sportback, and e-tron S	2023			
A6, A6 allroad, S6, RS 6 Avant, A7, S7, RS 7, S8, S8, Q7, SQ7, Q8, SQ8, and RS Q8	2023 – 2024	All	Remote Park Assist plus	
Q8 e-tron quattro, Q8 Sportback e-tron, SQ8 e-tron quattro, and SQ8 Sportback e-tron	2024			

Condition

Customer states:

Remote-controlled parking (remote park assist plus) is not working. The following message appears in the myAudi app when activating remote park assist plus:

"Connection to vehicle required - please make sure you are near your vehicle to start the function".

However, the customer is already near the vehicle.

Workshop findings:

No relevant DTCs are stored.



NOTICE

The event memory entry "B187A00: Cancel parallel parking assist (symptom number 98341)" has no influence with regard to this complaint.

Technical Background

A Software related issue in roof antenna control unit -JX3- may cause the remote park assist plus not to function.

Page 1 of 3



Technical Service Bulletin

Production Solution

Not applicable.

Service

Please perform a terminal 30 reset of the vehicle by disconnecting the 12 Volt battery -A-.

The procedure is described in the instructions in ElsaPro.

Please keep the 12V battery disconnected for approximately 20 minutes.

Warranty

Claim Tymay	44044 4 4044 4 450 00044				
Claim Type:	• 110 Up to 48 Months/50,000 Miles.				
	G10 for CPO Covered Vehicles – Verify Owner.				
	If the vehicle is outside of any warranty, this Technical Service Bulletin is informational only.				
Service Number:	9138				
Damage Code:	0040				
Labor Operations:	GFF	0150 0010	See SRT with associated operations		
Diagnostic Time:	GFF	0150 0060	Time stated on the diagnostic protocol (Max 50 TU)		
	Road test prior to the service procedure	No allowance	0 TU		
	Road test after the service procedure	No allowance	0 TU		
Claim Comment:	As per TSB 2071986/1				

All warranty claims submitted for payment must be in accordance with the *Audi Warranty Policies and Procedures Manual*. Claims are subject to review or audit by Audi Warranty.

Additional Information

All part and service references provided in this TSB (2071986) are subject to change and/or removal. Always check with your Parts Department and/or ETKA for the latest information and parts bulletins. Please check the Repair Manual for fasteners, bolts, nuts, and screws that require replacement during the repair.



Technical Service Bulletin

©2023 Audi of America, Inc. All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies, and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites without the prior expressed written permission of the publisher.