

Audi On-car analysis list from November, 10 2023

Please contact Audi Helpline before attempting repair

All topics have associated worksheets to be filled out and attached to the TAC ticket. Worksheets can be found at: [Elsa2Go>>Service References>> Search v4p](#)

| | Models | MY | Engine | Trans | Topic | Topic details |
|----|--------------------------------------|-----------|------------------------|-------|----------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| PT | Q3 | 2020-2021 | All | All | Coolant warning Lamp | Customer states they receive a low coolant warning in the cluster. Coolant level appears to be full in the reservoir <ul style="list-style-type: none"> Case does not relate to TSB 2061918 Photo showing reservoir level |
| | A6, A7, Q7, Q8, S4, S5 | 2019-2023 | 3.0L | All | Catalytic Converter Inspection , P042000: Catalyst System,Bank1 Efficiency Below | <ul style="list-style-type: none"> GFF Log with all fault codes and completed test plans. Oil and Fuel samples (Hazmat containers can be requested through TAC). After oil sample have been collected, oil and filter should be changed. VIN-4-Pin Worksheet with answers to questions |
| | All models with 3.0L engine (EA839) | 2021-2023 | 3.0L (EA839) | All | Abnormal/no sound from engine sound generator | <ul style="list-style-type: none"> Video/ sound recording of abnormal noise/ customer complaint from inside the vehicle before repair. Video/ sound recording while running sound actuator test Upload GFF log with executed test and relevant DTCs to GFF paperless Video/ sound record of noise from inside the vehicle after repair. |
| | A4 | 2023 | All | All | Coolant leak from expansion tank | Photo documentation of the source of the leak |
| | Q3 | 2019-2023 | All | All | P008700 Low fuel pressure | Applies to Q3 models within NVLW only <ul style="list-style-type: none"> DTC P008700 Attach completed worksheet on initial TAC contact. |
| | A6, A7, Q7, Q8, S4, S5 | 2020-2024 | EA839 3.0L 2.9L | All | Parts Block Belt tension damper 06M903133AA | Only applicable if no prior repairs to Starter generator/ belt drive system performed. See worksheet |
| | Q4 e-tron | 2022-2024 | All | All | Charging cable cannot be removed from the vehicle | See e-tron charging questionnaire worksheet |
| | e-tron Q and SB Q8 e-tron and SB | 2019-2024 | All | All | Vehicle cannot be charged, charge socket lock without function | See e-tron charging questionnaire worksheet |
| | SQ5, Q7, Q8, S6, S7, S4, S5, RS5, A8 | 2021-2024 | 3.0 L and 2.9L Engines | All | EA839 Coolant Pump leaking | Coolant pump leaking Photo and video documentation See worksheet |
| | Q5 | 2021-2023 | All | All | Q5 coolant resevor cap broken | Tank and cap needed See worksheet |
| EL | A6, A7, A8, Q7, Q8 | 2019-2024 | all | all | 48V BSG U046900 | PR Codes: 0K4 with VH2 OR 0K4 with VH3 See worksheet |
| | e-tron GT | 2022-2024 | All | All | Front side window inoperative | Customer concern that a front door module function is inoperative water test, inspect door harness and pillar connection |
| | SQ5 | 2018-2024 | All | All | Wire broke at air compressor V66 | DTC P089200 Broken/Damaged/Loose connection found at V66 (Suspension Compressor) T3DL |
| BD | e-tron Quattro e-tron SB | 2023-2024 | Any | Any | Noise from Front Door Trim Panel | Noise from front door trim panel while driving <ul style="list-style-type: none"> Video of noise before repair is performed Photos of repair |
| | A5 | 2023-2024 | Any | Any | Noise from Front Door speaker Grill | Noise from front door trim panel while driving <ul style="list-style-type: none"> Video of noise before repair is performed Photos of repair |