



# Preliminary Information

## PIT6074 Auxiliary Battery Not Charging

### Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Chevrolet	Silverado 2500HD/3500HD	2024	All	All	All	All
GMC	Sierra 2500HD/3500HD	2024	All	All	All	All

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

Involved Region or Country	North America
Additional Options (RPO)	Auxiliary Battery RPO K4Z
Condition	Some customers may comment that the Auxiliary Battery is not charging.
Cause	The cause of the condition may be a software anomaly.

### Correction:

Engineering is aware of this condition and is working on an updated software to remedy this concern.

### Version History

Version	1
Modified	Created on 10/11/2023



GENERAL MOTORS