



Bulletin No.: PIT6066  
Published date: 10/17/2023

## Preliminary Information

### PIT6066 Front License Plate Missing at PDI

Product Investigation Review Required

#### Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Chevrolet	Silverado EV	2024	All	All	All	All

Involved Region or Country	North America
Additional Options (RPO)	VK3
Condition	It may be discovered when performing the PDI on a vehicle that the front license plate bracket is not included with the dealer pack items. If the vehicle was delivered to a state that requires a front license plate or has option code VK3 it should be included.
Cause	Plant packaging error. This is NOT a transportation issue.

#### **Correction:**

Order license plate bracket part # 85131247 through the Technical Assistance Center.

Please contact TAC at Telephone Number US 1-877-446-8227 (Action Center prompt or Hybrid prompt) or Canada 1-800-263- 7740 for English or 1-800-263-7960 for French.

**Note: The labor claim below has no time included due to labor already being paid with PDI. Please file the labor claim to allow for payment of the bracket.**

#### Parts Information

Description	Part Number	Quantity
License Plate Bracket	85131247	1

#### Warranty Information

For vehicles repaired under the Bumper-to-Bumper coverage (Canada Base Warranty coverage), use the following labor operation. Reference the Applicable Warranties section of Investigate Vehicle History (IVH) for coverage information.

Labor Operation	Description	Labor Time
2086858	Install Missing Front License Bracket	0.0 Hr.

Labor Operation	Description	Labor Time
<b>*This is a unique Labor Operation for Bulletin use only.</b>		

### Version History

Version	1
Modified	10/17/2023 - Created on.



© 2023 General Motors. All Rights Reserved.