



Preliminary Information

PIT6079 Service Power Steering /No Assist Soon Message Illuminated on the IPC With DTC C1168

Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Chevrolet	Silverado EV	2024	All	All	All	All

Involved Region or Country	North America
Condition	A customer/driver could see a "Service Power Steering – No Assist Soon" message that displays on the IPC along with a DTC C1168 Power Steering Malfunction Level 1 Circuit stored in the electronic power steering (EPS) control module.
Cause	Software Anomaly

Correction:

GM engineering is aware of the issue and working on new software that will address this concern. A target release is scheduled for the 4th quarter of 2023.

Technicians are requested to clear codes from the EPC control module and return the vehicle back to the customer/driver.

If the DTC does not clear and returns immediately, please follow normal SI diagnostics.

Warranty Information

For vehicles repaired under the EV coverage, use the following labor operation. Reference the Applicable Warranties section of Investigate Vehicle History (IVH) for coverage information.

Labor Operation	Description	Labor Time
2889908	DTC Read and Code Clear of EPS Module	0.2 Hr.
*This is a unique Labor Operation for Bulletin use only.		

Version History

Version	1
Modified	10/24/2023 - Created on.



