



Preliminary Information

PIC6525 Speed Limit Sign Showing Dashes After Radio Update

[Proactive](#)

[Models](#)

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Cadillac	Lyriq	2023	All	All	All	All

Involved Region or Country	North America
Additional Options (RPO)	IVD
Condition	Some customers may comment that the speed limit sign in the IPC is showing dashes (--) after the radio was USB updated
Cause	This could be a radio software anomaly.

Correction:

If the radio is running USB software W38E-170.5.1-M166-SQBR3-187.2 and the customer has an active OnStar account with a data plan, do not replace any parts at this time.

To verify this software, select Settings>System>About>Build Number.

If Google services are not operational (Maps, Playstore, Google Assistant) please follow Service Information for normal diagnostics.

Version History

Version	1
Modified	10/26/2023 - Created On.

