

Seal, Weather Trim Strip (B-Pillar Trim) on Rear Doors Detaching

Topic number	LI72.12-P-076175
Version	2
Function group	72.12 - Rear door
Date	11/6/23
Validity	MODEL 206 206.0 FIN "F" up to manufacturing date: 18 January 2023 206.0 FIN "R" up to manufacturing date: 23 February 2023
Reason for change	Part numbers A 206 690 67 00 and A 206 690 68 00 replaced by A 206 690 75 04 und A 206 690 76 04

Complaint

Seal, B-pillar trim on rear doors cracked in upper area, see picture 1.

Attachments	
File	Description
Bild 1.jpg	



Cause

Production deviation at supplier of B-pillar trim.

Remedy

Replace B-pillar trim through optimized parts.

WIS-References

Document number	Title	Note
AR72.12-P-1713WT	Remove/install front trim strip from window frame of rear door	

Symptoms

Body > Door/Flap > Door > Door > Seal cracked/torn

Body > Door/Flap > Door > Trim > Loose

Parts

Part number	ES1	ES2	Designation	Quantity	Note	EPC
A2066907504			Outer left B-pillar trim molding	1		X
A2066907604			Outer right B-pillar trim molding	1		X

XENTRY Tips

Operation numbers/damage codes				
Op. no.	Operation text	Time	Damage code	Note