

Subject: Engineering Information – Rear Compartment Lid Does Not Open and/or Opens Intermittently

This EI has been revised to end the need for gathering information from the field. Please discard PIE0763.

Brand:	Model:	Model Year:		VIN Breakpoint:		Engine:	Transmission:
		from	to	from	to		
Chevrolet	Camaro	2023	2024	—	—	—	—

If you encounter a vehicle with the above condition, refer to SI for further diagnosis as there will be service Bulletin soon to follow.

Version	2
Modified	Released October 02, 2023 Revised November 17, 2023 – Ended the need for gathering further information from the field.