

| | |
|----------------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| Reference | SSM76106 |
| Models | Defender / L663 |
| Title | Exhaust Tailpipe Corrosion |
| Category | Engine |
| Last modified | 01-Nov-2023 00:00:00 |
| Symptom | 403000 Exhaust System Concerns |
| Attachments | SSM76106 Attachment Exhaust Tailpipe Corrosion.pdf (SSM76106 Attachment Exhaust Tailpipe Corrosion.pdf) |
| Content | <p><u>Model / Model Year / Derivative</u></p> <p>Defender / 21MY onwards / 5.0L AJ133G2 P8 S/C only</p> <p><u>Situation:</u></p> <p>JLR Engineering investigations have received reports of visible corrosion around the outlet of the exhaust tailpipe prior to Pre Delivery Inspection (PDI). See attached example image showing light corrosion.</p> <p><u>Cause:</u></p> <p>Currently under evaluation.</p> <p><u>Action:</u></p> <p>Follow the instruction(s) below.</p> <p><u>SERVICE INSTRUCTION:</u></p> <p>1. Where mild corrosion is visible on the exhaust tail pipe, clear away the corrosion using a non metallic scouring pad or suitable mild cutting paste.</p> |

(Ref 000379678)

anBhdHRkcnM7MjAyMy0xMj0wN1QxOTowOT01OS4wMTFhO2EzNjYyMjYyNDguMTAzOw==