WPC6 Workshop Campaign - Replacing driver airbag unit

WPC6 Workshop Campaign - Replacing driver airbag unit

Please note that this campaign is for parts analysis purposes only. The campaign will be closed once the part threshold is reached. We expect to close this campaign after 150 airbags have been sent back to Germany for analysis. All airbags removed from vehicles must be returned to your PC's facing PDC.

ID Number	WPC6
Models	Cayenne (92A) Macan (95B)
Model Years	2015
VIN List	Attached
Number of affected VINs	587
Issue Description	The airbags of the affected vehicles must be exami- ned in order to validate the results of vehicle testing for long-term quality.
	The corresponding airbags must be replaced in accor- dance with the assigned scope and the existing air- bag must be returned to Germany for further laborato- ry analyses.
What should Porsche Centers do?	Please arrange for this measure to be carried out as soon as possible on affected vehicles.
	As of the time of this posting (11/3/23) the remedy is now available. Parts must be ordered via PPL with a PRMS Parts Support ticket for release. Please return all airbags removed from vehicles to your PC's facing PDC. Do not scrap any airbags.
TI Number	No. 35-23

Required parts

Please note that the removed airbag units must be returned.

For details on the return of the airbag units, please refer to the Technical Information (TI) and instructions in WWS.

Part number	Designation - Application site	Quantity/vehicle	Parts return
V04015001MA5Q0	Driver airbag unit - Cayenne - Black	1	Yes
V04015001MA6W0	Driver airbag unit - Cayenne - Luxor beige	1	Yes
V04015001MBA34	Driver airbag unit - Macan - Black	1	Yes
V04015001MC6W0	Driver airbag unit - Macan -Luxor beige	1	Yes

Warranty processing

Validity:

The present workshop campaign will be carried out until 150 airbag units have been replaced and then the campaign will be closed.

Please note that warranty claims can only be processed up to this time.

Scope 1: Replacing driver airbag unit

- Cayenne
- with driver airbag unit in black

Damage Code	WPC6
Repair Code	2
Labor time	34 TU

Scope 2: Replacing driver airbag unit

- Cayenne
- with driver airbag unit in beige

Damage Code

Repair Code	2
Labor time	34 TU

Scope 3: Removing and installing the driver airbag unit

Cayenne

Damage Code	WPC6
Repair Code	1
Labor time	28 TU

Scope 4: Replacing driver airbag unit

- Macan
- with driver airbag unit in black

Damage Code	WPC6
Repair Code	2
Labor time	34TU

Scope 5: Replacing driver airbag unit

- Macan
- with driver airbag unit in beige

Damage Code	WPC6
Repair Code	2
Labor time	34TU

Scope 6: Removing and installing the driver airbag unit

Macan

Damage Code	WPC6
Repair Code	1
Labor time	28 TU

Please enter the campaign carried out in the warranty and maintenance book for the vehicle.

Attachments

1. VIN_List_Report_WPC6_2023-11-03_V2.xlsx