

**Subject: Engineering Information - (EI Lite) - (Pictures Only) Engine Oil Under Vehicle and/or Engine Oil Leak from the Oil Pan and LCE Joint**

*This PI has been revised to end the need for gathering information from the field. Please discard PIE0758.*

Brand:	Model:	Model Year:		VIN Breakpoint:		Engine:	Transmission:
		from	to	from	to		
Buick	Encore GX	2023	2023	—	—	Equipped with 1.3L (RPO L3T) <b>ONLY</b>	—
Chevrolet	Trailblazer (VIN M)						

If you encounter a vehicle with the above condition, refer to SI for further diagnosis.

<b>Version</b>	2
<b>Modified</b>	Released August 15, 2023 Revised November 28, 2023 - Ended the need for gathering further information from the field.