



# Preliminary Information

## PIT6055A HUMMER EV Service Driver Assist Message with DMS DTC: U3000 or B0126

Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
GMC	HUMMER EV	2022 - 2024	All	All	All	All
GMC	HUMMER EV SUV	2024	All	All	All	All

Involved Region or Country	North America
Condition	<p>A customer may comment of a "Service Drivers Assist" message, upon inspection one or more of the following DTC's may be found in the K180 Drivers Monitoring System Module (DMSM).</p> <p>B0126 SYM 49 Current/History, U3000 SYM 44 Current/History, U3000 SYM 49 Current/History.</p> <p><b>Note: If you experience a Service Drivers Assist" message that does not have one of the following DTC's above, refer to normal SI diagnosis.</b></p>
Cause	Software Anomaly

Correction:

Reprogram the K180 Drivers Monitoring System Module (DMSM) to the latest software released in SPS.

Warranty Information

For vehicles repaired under the Bumper-to-Bumper coverage (Canada Base Warranty coverage), use the following labor operation. Reference the Applicable Warranties section of Investigate Vehicle History (IVH) for coverage information.

Labor Operation	Description	Labor Time
-----------------	-------------	------------

2810865	K180 Driver Monitoring System Control Module Reprogramming with SPS	Use Published Time
---------	--	--------------------

Version History

Version	2
Modified	09/12/2023 - Created on. 11/14/2023- Update PI to add software fix that is now available



© 2023 General Motors. All Rights Reserved.