

## STAR ONLINE PUBLICATION
















Case Number: S1808000057 Rev. A

Release Date: October 2023

**Symptom/Vehicle Issue:** Inspecting And Disconnecting Negative Battery Cables On ESS Vehicles

**Discussion**: When performing circuit testing that requires disconnecting the battery(s) on ESS vehicles, disconnect both negative battery connections from the primary and auxiliary battery Fig 1, Fig 2, Z802 circuit.



This document does not authorize warranty repairs. This communication documents a record of past experiences. STAR Online does not provide any conclusions about what is wrong with the vehicle. Rather, it captures all previous cases known that appear to be similar or related to the vehicle symptom / condition. You are the expert, and you are responsible for deciding on the appropriate course of action.

Contact STAR Center, or your Technical Assistance Center Via TechConnect, eCONTACT or Service Library entry if no solution is found.

Stellantis US LLC Version 4.5 07/22/2022



## STAR ONLINE PUBLICATION


















Fig 2

This document does not authorize warranty repairs. This communication documents a record of past experiences. STAR Online does not provide any conclusions about what is wrong with the vehicle. Rather, it captures all previous cases known that appear to be similar or related to the vehicle symptom / condition. You are the expert, and you are responsible for deciding on the appropriate course of action.

Contact STAR Center, or your Technical Assistance Center Via TechConnect, eCONTACT or Service Library entry if no solution is found.

Stellantis US LLC Version 4.5 07/22/2022