

STAR ONLINE PUBLICATION















Case Number: S2309000011

Release Date: October 2023

Symptom/Vehicle Issue: Customer may complain "Service Engine – See Dealer" message displays in cluster

- 1. Engineering is aware of the issue and working toward resolution.
- 2. If the customer is experiencing this message, premium fuel (91+) may be required while driving in heavily loaded or hot conditions until an engineering update becomes available.

This document does not authorize warranty repairs. This communication documents a record of past experiences. STAR Online does not provide any conclusions about what is wrong with the vehicle. Rather, it captures all previous cases known that appear to be similar or related to the vehicle symptom / condition. You are the expert, and you are responsible for deciding on the appropriate course of action.

Contact STAR Center, or your Technical Assistance Center Via TechConnect, eCONTACT or Service Library entry if no solution is found.

Stellantis US LLC Version 4.5 07/21/2022