

Technical Service Bulletin

48 Steering system cannot be "started"

48 23 58 2072303/1 December 13, 2023.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
A6, A6 allroad, S6, RS 6, A7, S7, RS 7, A8, S8, Q5, Q5 e quattro, Q5 Sportback, SQ5, SQ5 Sportback, Q7, SQ7, Q8, SQ8, and RS Q8	2023 – 2024	All	Not Applicable

Condition

Customer states:

No Customer complaint is noted; it is found during diagnostic work.

Workshop findings:

The newly installed steering system cannot be "started".

Technical Background

Not applicable.

Production Solution

Gradual introduction in production.

Service

SVM Update Instructions

- 1. Follow all instructions in TSB 2011732: 00 Software Version Management (SVM), operating instructions.
- 2. Update the J500 (address word 0044) using the SVM action code as listed in the table below, if necessary:

Model	Old Software Part Number	Old Software Version	New Software Part Number	New Software Version	SVM Code Input	
			(or higher)	(or higher)		
A6, A7, A8, Q5, Q7, Q8	4N0909144H	0511	4N0909144H	0512	44A040	

Page 1 of 2



Technical Service Bulletin

Warranty

Claim Type:	 110 Up to 48 Months/50,000 Miles. G10 for CPO Covered Vehicles – Verify Owner. If the vehicle is outside of any warranty, this Technical Service Bulletin is informational only. 					
Service Number:	4835					
Damage Code:	0040					
Diagnostic Time:	Software Update (Includes checking for DTCs)	0150 0000	Time stated on the diagnostic protocol (Max 40 TU)			
	Road test prior to the service procedure	No allowance	0 TU			
	Road test after the service procedure	No allowance	0 TU			
Claim Comment:	As per TSB 2072303/1					

All warranty claims submitted for payment must be in accordance with the *Audi Warranty Policies and Procedures Manual*. Claims are subject to review or audit by Audi Warranty.

Additional Information

All part and service references provided in this TSB (2072303) are subject to change and/or removal. Always check with your Parts Department and/or ETKA for the latest information and parts bulletins. Please check the Repair Manual for fasteners, bolts, nuts, and screws that require replacement during the repair.

©2023 Audi of America, Inc. All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies, and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites without the prior expressed written permission of the publisher.