

Subject: Engineering Information – Rear Compartment Lid Does Not Open and/or Opens Intermittently

This EI has been revised to add the service bulletin number reference. Please discard PIE0763A.

Brand:	Model:	Model Year:		VIN Break-point:		Engine:	Transmission:
		from	to	from	to		
Chevrolet	Camaro	2023	2024	—	—	—	—

If you encounter a vehicle with the above condition, refer to Service Bulletin Number 23-NA-211 in SI.

Version	3
Modified	Released October 02, 2023 Revised November 17, 2023 – Ended the need for gathering further information from the field. Revised December 05, 2023 – Added the service bulletin number reference.