

MAS003773 RU 23-51

**RAPID UPDATE**

FROM: Maserati TSO

TO: Maserati Network



**Maserati**

PERSONAL SERVICE LAB

MASTERS OF CARE

# Rapid Update 664 Granturismo – Replacement of front A-pillar coverings

TECHNICAL SERVICE OPERATIONS



DATE: NOVEMBER 23 2023

Certain Maserati GranTurismo (M189) MY24 listed in MODISCS+ are involved in a Rapid Update to carry out a procedure to replace both A-pillar trims.

This action is deemed necessary due to the identification of a limited batch of components that have been installed. There is a concern regarding potential fabric wrinkles resulting from a deviation in the manufacturing process. The procedure therefore consists in replacing the existing components with new ones.

We remind you that all the Rapid Updates must be performed within the first workshop visit, regardless of the Mandatory setting set in Modis, as required by Maserati policies.

Also, for vehicles in Stock Dealer / PDI, it is necessary to carry out all action operations before delivery to the end customer, as required by the White Book and explicitly reported in the Pre-delivery checklist.

**Please read and review this bulletin first before ordering parts and/or starting the procedure.**

Contact your Regional AfterSales Manager (RAM) or the Technical Support Helpdesk if you have any questions.

Thank You for your continued support and cooperation.

Maserati Americas  
Aftersales Dept.

# Procedure

 All images shown in this bulletin are for illustrative purposes only

1. Always check ModisCS+ to see if the vehicle is involved in this action and if it has not been previously performed.
2. Always add interior protection to protect the interior.
3. Replace both A-pillars following the procedure in the workshop manual:
  - **09.44.001 RIGHT WINDSHIELD PILLAR COVERING. Removal-Reattachment or Replacement**
  - **09.44.002 LEFT WINDSHIELD PILLAR COVERING. Removal-Reattachment or Replacement**



4. Repeat the operation on the other side. (Both A-pillars)
5. Re-install all removed parts following the procedure in reverse order.
6. Procedure complete.

## Spare Parts

To carry out this action, please order the following PNs, referring to the spare parts catalog and following the indications contained in the attached Vin-List.

**Please refer to the attached VIN list to verify the accurate Part Numbers that should be ordered for each respective VIN**

Complete VIN	Material Color	RH part number	LH part number	Press CTRL+F to search for the VIN
ZAMBMVBB0RX431219	GUILFORD BLACK	6702880680	6702880600	
ZAMBMVBB0RX431298	GUILFORD BLACK	6702880680	6702880600	
ZAMBMVBB0RX432676	GUILFORD BLACK	6702880680	6702880600	
ZAMBMVBB0RX432693	GUILFORD BLACK	6702880680	6702880600	
ZAMBMVBB0RX435898	ALCANTARA BLACK	6702880650	6702880570	
ZAMBMVBB0RX435903	GUILFORD BLACK	6702880680	6702880600	
ZAMBMVBB0RX436713	GUILFORD BLACK	6702880680	6702880600	
ZAMBMVBB0RX436744	GUILFORD BLACK	6702880680	6702880600	
ZAMBMVBB0RX436758	GUILFORD BLACK	6702880680	6702880600	

## Warranty Claim

Complete the Warranty Claims as follows:

Description	Code
Rapid Update Number	664
Warranty code	23
Error code	063
Component Code	9.44.001
Operation Code <ul style="list-style-type: none"> <li>▪ Component replacement (2 sides)</li> </ul>	9.44.001.A (0.10 h)