

		Tesla, Inc. Service Bulletin		<i>Replace Front Body Controller Module</i>
SB-23-17-011 November 9, 2023				
Classification		Section/Group	Mobile Service	
Campaign Bulletin		17 - Electrical	Can Perform (where permitted)	All
Model Year	Model	Country/Region	Build Location	
2023	Model Y	United States, Canada	Fremont, Giga Austin	
The model(s) and model year(s) listed are a general approximation of the affected VIN list. Refer to the VIN/Bulletin Tracker or Customer/Vehicle profile to determine applicability of this bulletin for a particular vehicle.				

Campaign Bulletin: This campaign bulletin addresses a non-safety-related condition and provides recommended technical diagnosis and repair procedures. Apply this procedure to the applicable vehicles.

Condition

Certain Model Y vehicles may require replacement of the front body controller module which may impact the ability to detect fuse failure and show an alert for "Condition detected with a vehicle controller".

Correction

Replace the front body controller module.

Correction Description	Correction	Time
SB-23-17-011 Not Applicable	S012317011	0.00
Replace Front Body Controller Module	S022317011	0.96

Part Number	Description	Quantity
Parts Required		
One of the following:		
1866750-00-A	ASY. FRONT CONTROLLER GEN 3	1
1866750-20-A	ASY. FRONT CONTROLLER GEN 3	1
1886750-99-A	RWK ASY. FRONT CONTROLLER GEN 3	1
And:		
1137934-00-C	BOLT - HF - M6X16 - [109] - G0109 - ADH - MAT	2
1128091-00-B	SCREW HF M6X16	1
These part numbers were current at the time of publication. Use the revisions listed or later, unless otherwise specified in the Parts Catalog .		

Procedure

Replace the front body controller module (refer to Service Manual procedure [17152912](#)).