

<b>REFERENCE:</b>	<b>TSB:</b> 08-043-23 <b>GROUP</b> 08 - Electrical	<b>Date:</b>	February 8, 2023	<b>REVISION:</b>	08-178-22
<b>VEHICLES AFFECTED:</b>	2020 - 2022 (BV) Jeep Renegade This bulletin applies to vehicles built on or after August 25, 2020 (MDH 0825XX) and built on or before <b>**March 14, 2022 (MDH 0314XX)**</b> equipped with 1.3L I4 Turbo PHEV Engine (Sales Code EYG) and Auto Power Folding Mirrors (Sales Code LFF).	<b>MARKET APPLICABILITY:</b> <input type="checkbox"/> NA <input checked="" type="checkbox"/> MEA <input type="checkbox"/> SA <input type="checkbox"/> IAP <input checked="" type="checkbox"/> EE <input type="checkbox"/> CH			
<b>CUSTOMER SYMPTOM:</b>	The customer may describe the power folding mirrors may intermittently not power fold or unfold.				
<b>CAUSE:</b>	<ul style="list-style-type: none"> <li>Folding mirror switch.</li> </ul>				

This bulletin supersedes Technical Service Bulletin (TSB) 08-178-22, date of issue October 01, 2022, which should be removed from your files. All revisions are highlighted with **\*\*asterisks\*\*** and include revised build date

This Technical Service Bulletin (TSB) has also been released as a Rapid Service Update (RSU) 22-178, date of issue October 01, 2022. All applicable Sold and Un-Sold RSU VINs have been loaded. To verify this RSU service action is applicable to the vehicle, use VIP or perform a VIN search in DealerCONNECT/Service Library. All repairs are reimbursable within the provisions of warranty. This RSU will expire 18 months after the date of issue.

**REPAIR SUMMARY:**

This bulletin involves replacing the power folding mirror/window switch assembly on the door.

**CLAIMS DATA:**

Labor Operation No:	Labor Description	Skill Category	Labor Time
08-80-54-95	Switch and Bezel, Front Door - Replace (1 - Semi-Skilled)	6 - Electrical and Body Systems	0.2 Hrs.
Failure code	ZZ	Service Action	

**SPARE PARTS:**

Qty	Part No.	Description	Notes
1	7MS28LXHAA Mopar 735768399 Enlarged Europe	Switch, Power Folding	(Right Hand Drive)
1	7MS33LXHAA Mopar 735768403 Enlarged Europe	Switch, Power Folding	(Left Hand Drive)

**DIAGNOSIS:**

If a customer's VIN is listed in VIP or your RSU VIN list, perform the repair. **This RSU only applies to vehicles on the RSU VIN list.**

**REPAIR PROCEDURE:**

**NOTE: High Voltage power down is not needed for this repair.**

1. Replace the driver's door switch assembly. Refer to the detailed service procedures available in DealerConnect> Service Library under: Service Info> 08 - Electrical / 8N - Power Systems / Power Windows / Switch, Power Window / Removal and Installation.

**POLICY:**

Reimbursable within the provisions of the warranty.

*This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of FCA US LLC.*