



2024 Durango D326RLT Wall Mount TV Bracket

It has been brought to our attention that the following units may have a rear wall TV bracket that was manufactured incorrectly. This may cause the TV to fall off the wall during transit, damaging the interior of the RV. A replacement TV bracket will be shipped to you for replacement.

Part number **154026** will be sent for this repair.

The following flat rate codes should be used when filing the warranty claim:

R/R TV FRC **9941** time 0.30

R/R TV bracket Stationary FRC **9957** time 0.50

Total time allotted 0.80

4EZFD382XR6100265
4EZFD3821R6100266
4EZFD3823R6100267
4EZFD3825R6100268
4EZFD3827R6100269
4EZFD3823R6100270
4EZFD3825R6100271
4EZFD3827R6100272
4EZFD3824R6100424
4EZFD3826R6100425
4EZFD3828R6100426
4EZFD382XR6100427
4EZFD3821R6100428
4EZFD3823R6100429
4EZFD382XR6100430
4EZFD3823R6100432
4EZFD3825R6100433
4EZFD3827R6100434

This request is valid for 60 days. Damages caused due to the RV if this work request is not completed will not be considered **WARRANTABLE**.

December 8, 2023