

HEADLAMP WASHER NOZZLES LEAK FLUID WHEN NOT IN USE

Customer Voice:

- The headlamp washer nozzles seep fluid when not in use and leave residue on the bezels.

Technical Description:

- This may be caused by a headlamp washer nozzle check valve that is not sealing fully.

Status:

- A change to the check valve design has been introduced to robustly address this concern.
- Guided flows have been published on TOPIx Cloud to provide repair guidance.
- The check valves are only serviced as a complete washer hose assembly.
- The procedure for replacing the headlamp washer hoses is published in the **Workshop Manual Section: 501-16: Wiper and Washer > Removal and Installation > Headlamp Washer Fluid Hose.**

Defender

- 20 - 23MY Defender

