STELLANTIS PARTS & SERVICES		Technical Service Bulletin (TSB) Dual-Pane Sunroof Leaking			
REFERENCE:	TSB: 23-102-23 GROUP: 23 - Body	Date:	September 28, 2023	REVISION:	_
VEHICLES AFFECTED:	This bulletin applies to vehicles built on or before February 06, 2023 MDH 0206XX) equipped with a Dual-Pane Panoramic Sunroof (Sales Code GWJ).		MARKET AF	PPLICABILITY: CH IAP MEA	
CUSTOMER SYMPTOM:	Dual-pane sunroof is leaking Fig. 1.				
CAUSE:	Wind deflector assembly.				



Fig. 1
Wind Deflector Getting Trapped In Sunroof Panel Causing Leak

REPAIR SUMMARY:

This bulletin involves replacing the dual-pane wind deflector assembly with an updated design.

23-102-23 -2-

CLAIMS DATA:

Labor Operation No:	Labor Description	Skill Category	Labor Time
23-30-66-96	Dual-Pane Wind Deflector - Replace (2 - Skilled)	6 - Electrical and Body Systems	0.3 Hrs.
Failure Code	ZZ	Service Action	

SPARE PARTS:

Qty	Part No.	Description	Notes
1	68518680AC	Windscreen, Sunroof	Dual-Pane Wind Deflector

DIAGNOSIS:

If the customer describes any of the symptom listed above in the customer symptom section, perform the Repair Procedure.

REPAIR PROCEDURE:

 Replace the dual-pane wind deflector. Refer to the detailed service procedures available in DealerCONNECT/Service Library under: Service Info>23 - Body / Sunroof, Dual Pane / Deflector, Wind / Removal and Installation.

POLICY:

Reimbursable within the provisions of the warranty.

This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of FCA US LLC.