

GPOP - Issue Review System

Part Number: 68338342A\$

Part Description: Steering Drag Link

Issue If drag link had been welded due to V06 recall repair and there is an alignment concern, prior to drag link replacement ensure that the welded draglink toe setting procedure has been followed first. ~

~

Service Library:

02 - Front Suspension / Wheel Alignment / Standard Procedure / TOE SETTING
PROCEDURE FOR TRUCKS WITH DRAG LINK RECALL WELD ~