



STAR ONLINE PUBLICATION



Case Number: S2308000148

Release Date: November 2023

Symptom/Vehicle Issue: Horn Sounding When Flashing a Body Control Module (BCM)

Technician Observation: On some occasions the horn may sound when flashing or servicing a BCM on a GG – Hornet or a GC – Tonale.

Discussion: To prevent the horn from sounding when servicing the BCM, remove the horn fuse or relay.

*****DO NOT DISCONNECT THE 12V BATTERY WHEN THE HORN SOUNDS FROM BCM SERVICE.**

Remove Fuse F10 - Fuse cavity locations are printed on the inside of the power distribution center cover Fig 1 and 2.




Fig 1

This document does not authorize warranty repairs. This communication documents a record of past experiences. STAR Online does not provide any conclusions about what is wrong with the vehicle. Rather, it captures all previous cases known that appear to be similar or related to the vehicle symptom / condition. You are the expert, and you are responsible for deciding on the appropriate course of action.

Contact STAR Center, or your Technical Assistance Center Via TechConnect, eCONTACT or Service Library entry if no solution is found.



STAR ONLINE PUBLICATION




Fig 2

This document does not authorize warranty repairs. This communication documents a record of past experiences. STAR Online does not provide any conclusions about what is wrong with the vehicle. Rather, it captures all previous cases known that appear to be similar or related to the vehicle symptom / condition. You are the expert, and you are responsible for deciding on the appropriate course of action.

Contact STAR Center, or your Technical Assistance Center Via TechConnect, eCONTACT or Service Library entry if no solution is found.