

Volvo Car USA LLC	Parts Bulletin	
Bulletin Title	Group	CAT/NO
Delivery Action D10260: FLC2	38	D10260
Model Year 2024 S60, XC90, XC40		
Car Market	Issue Date	Status Date
United States and Canada	12/13/23	12/13/23
Revisions	Page	
	Page 1 of 1	

Reference Bulletin: QB D10260

Volvo Cars USA LLC and Volvo Cars Canada LTD on behalf of the Volvo Car Corporation has decided to launch Delivery Action D10260: Forward Looking Camera 2 (FLC2) on certain model year 2024 S60, XC40, and XC90 vehicles.

Volvo Cars investigations have identified that the wrong part number has been assembled for the FLC2 and you will not be able to perform PDS software.

The corrective action is to replace the FLC2 according to VIDA instruction.

A total of 12 U.S. and 1 Canadian vehicles are eligible for this delivery action.

Parts Required:

Part Number	Qty	Failing Part	Description
32410083	1	F	Camera
32327195	0-1		FLC2 Reload XC40/C40
32358739	0-1		FLC2 Reload S60
32327814	0-1		FLC2 Reload XC90