

Technical Journal

TITLE:

“Sticky” rear brake pads

REF NO: TJ 36169.4.0	ISSUING DEPARTMENT: Technical Service	CAR MARKET: United States and Canada	
PARTNER: 3 US 7510 Volvo Car USA		ISSUE DATE: 2023-02-02	STATUS DATE: 2023-02-06
FUNC GROUP: 5125	FUNC DESC: Brake pad; brake pad kit	Page 1 of 2	

“Right first time in Time”

Rows beginning with * are modified

Note! If using a printed copy of this Technical Journal, first check for the latest online version.

DESCRIPTION:

* Updated Service information.

If the customer experience loud sound and/or heavy vibrations from the rear , please follow advice under Service.

CSC Customer Symptom Codes

Code	Description
1P	Brakes/Unusual noise/Rear
V3	Brake pedal/Pulsations
V4	Brakes/Vibration/shudder/While braking

DTC Diagnostic Trouble Codes

Vehicle Type

Type	Eng	Eng Desc	Sales	Body	Gear	Steer	Model Year	Plant	Chassis range	Struc Week Range
536	ED	E400V6					2021-2023		-	202037-202246
539	ED	E400V6					2022-2023		-	202139-202246

Technical Journal 36169.4.0

SERVICE:

If the symptom is confirmed, proceed with replacement of the rear brake pads according to the VIDA.

Note: In some cases, Brake discs may need to be replaced.

If the Brake disc is judged as damaged (visual check), proceed with replacement according to the VIDA

Note: This issue normally occurs on the inboard pads, which can be difficult to see. If the customer's symptoms match this TJ, completely remove the pads from the caliper brackets to be able to thoroughly inspect all the pad and rotor friction surfaces.

Warranty claim info:

To get warranty claim accepted for a job described in this TJ, please use following data:

VST OP Number: 51204-0

VST Operation Number

VST Operation Number	Description
51204-0	Brake pads rear replace

VEHICLE REPORT:

Yes, please submit a Vehicle Report if the service solution described in this TJ has no effect. Use concern area "Vehicle Report" and sub concern area "Support not needed", use function group 5125.