



# Service Bulletin

Bulletin No.: 21-NA-195

Date: January, 2024

## INFORMATION

**Subject:** Information on Wheel Speed Sensor Harness Routing

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Chevrolet	Express	2020	2021	—	—	—	—
GMC	Savana						

<b>Involved Region or Country</b>	North America, Israel, Middle East
<b>Condition</b>	Technicians may find that when replacing the rear speed sensor harness, the new harness is shorter than the original harness.
<b>Information</b>	<div style="text-align: center;"> </div> <p style="text-align: right;">5883909</p> <p>When replacing the rear wheel speed sensor harness on some 2021 Express/Savana vans, the replacement part may be shorter than the original part being replaced. Engineering has made a change to the routing of the rear wheel speed sensor harness to prevent the chance of abrasion. The graphics above show examples of the old (1), and new (2) routing.</p>

**Important: Service agents must comply with all International, Federal, State, Provincial, and/or Local laws applicable to the activities it performs under this bulletin, including but not limited to handling, deploying, preparing, classifying, packaging, marking, labeling, and shipping dangerous goods. In the event of a conflict between the procedures set forth in this bulletin and the laws that apply to your dealership, you must follow those applicable laws.**

<b>Version</b>	2
<b>Modified</b>	Released August 23, 2021 Revised January 04, 2024 - Added 2020 Model Year.

